

EXHIBIT 3 – MANDATORY SITE VISIT DIRECTIONS

1. Address:

Snapfinger AWTF
4124 Flakes Mill Road
Decatur, GA 30294

2. **REQUIRED PPE:** hard bottom shoes that can get dirty, as well as hard hat, safety vest and safety glasses. We have these PPE items (except shoes) should you not have them.
3. When entering the plant:
 1. Come in through the main gate, all vehicle occupants will need to show DeKalb badge (or driver's license if no badge).
 2. Continue straight, you may need to show badge again at 2nd guard shack.
 3. Continue straight, you will come to stop sign, continue straight.
 4. After stop sign you will see a lot with trailers on left, pull into lot and around to the right, park as closely as possible.
 5. Enter the 1st trailer (DeKalb's trailer).
4. If you have not done so already, you will need to sign the Contractor's (Archer Western's) release form upon arrival. We will have a form printed for you.